

Engine Maintenance Log

Date	Mileage	Description of Service

Please contact the Hyundai Canada Consumer Affairs at **1-866-620-7521** if you have any questions regarding the information in this booklet.

Additional information can be found at HyundaiCanadaThetaEngineSettlement.com

Thank you for choosing Hyundai.

PLEASE KEEP THIS BROCHURE IN YOUR HYUNDAI VEHICLE'S GLOVEBOX WITH YOUR OWNER'S MANUAL



**INFORMATION ABOUT
THE ENGINE IN YOUR
HYUNDAI VEHICLE**





Software Upgrade: Knock Sensor Detection System

Hyundai, working in conjunction with one of the world's leading engineering and scientific consulting firms, has developed new engine monitoring technology called a "knock sensor detection system."

This software is designed to detect early signs of excessive main engine bearing and/or connecting rod bearing wear within the engine's rotating assembly, which is ordinarily associated with an engine knocking noise.

The system will detect a knocking noise and will then notify the driver via dashboard warning lights, as well as place the vehicle into a reduced power, engine protection mode. The vehicle should be taken to a Hyundai dealership immediately if the dashboard warning lights illuminate and the vehicle goes into engine protection mode.

This technology is now available for your vehicle at no cost to you. If you have not done so, please visit a Hyundai dealership to receive this software update.



Lifetime Warranty

Hyundai is also providing limited lifetime warranty coverage for certain engine repairs for original and subsequent owners of the following vehicles, provided the software update on the previous page has been completed: 2011-2019 Sonatas, 2013-2019 Santa Fe Sports, and 2014, 2015, and 2019 Tucsons. The lifetime warranty covers any damage to the short block assembly (consisting of the engine block, crankshaft and bearings, connecting rods and bearings, and pistons) caused by a connecting rod bearing failure; and any damage to the rest of the long block assembly caused by a connecting rod bearing failure.

Regular maintenance is essential to obtaining the highest level of performance, safety, and reliability from your Hyundai. It is especially important to routinely check your vehicle's engine oil level and regularly replace the engine oil and oil filter (see your Owner's Manual to determine how often you should change your vehicle's oil and filter - at least every 12,000 kilometres under normal usage and every 8,000 kilometres under normal usage for turbo vehicles). Maintaining your vehicle according to the Owner's Manual is required to ensure that your warranty coverage remains intact. You should keep detailed records of vehicle maintenance, including date of service, mileage at time of service, and a description of service and/or parts installation performed. The scheduled maintenance log in this brochure can help you document this information.

If you sell your vehicle, be sure to give your maintenance records to the new owner.

Hyundai will not deny a warranty claim solely because you do not have your records to show that you maintained your vehicle. However, damage or failure caused by an owner's neglect is not covered under warranty, including the lifetime warranty given by Hyundai in connection with the knock sensor software update described in this brochure.

In addition to the Lifetime Warranty, you may be eligible to receive compensation for future out-of-pocket expenses that are reasonably related to a connecting rod bearing failure or for related repair delays. Also, in the unlikely event you experienced an engine compartment fire, you may qualify for compensation. Please refer to the settlement website (HyundaiCanadaTheaEngineSettlement.com) or call **1-866-683-5860** for additional details on reimbursement eligibility and how to submit a claim.

Prospective buyers wishing to confirm whether there is applicable engine warranty coverage should call **1-866-620-7521**.

